

Last Vehicle Status Update: June 14, 2024 02:26 PM
*Note: Do not use as a pressure gauge

Refresh

Odometer



2246 Miles

High Voltage Battery



Battery State of Charge : 60%
Battery Range : 180 Miles

Tire Pressure (PSI)*



Recommended Tire Pressure(cold)
Front : Unknown | Rear : Unknown

12V Battery



Battery State of Charge : 83%
Battery Voltage : 13.8V

April 2024

Sun	Mon	Tue	Wed	Thu
	1	2	3	4
7	8	9	10	11
14	15 OTA	16 !	17 !	18
21	22 !	23	24	25
28	29	30		

May 2024

Sun	Mon	Tue	Wed	Thu
			1	2
5	6	7	8	9 !
--	13 !	14 ! !	15	16
19	20 !	21 !	22	23 ! !
26	27 !	28	29 !	30

June 2024

Sun	Mon	Tue	Wed	Thu
2	3 !	4	5	6
9	10	--	12 ! !	13 ! !
16	17	18	19	20
23	24	25	26	27
30				

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date Time Odometer	Event Description	Module	DTC	FT : SB	TSB/GSB/SSM	Send to Search	Description
------------------------	-------------------	--------	-----	---------	-------------	----------------	-------------

Time : 05:13 PM

Odometer : 2246 mi

★ ABS

U0401 : 86 : 28

★ CMR

B15E1 : 97 : 0C

SSM

★ IPMA

U2108 : 68 : 28

★ IPMA

U0401 : 86 : 28

★ OCSM

U0401 : 00 : 28

★ PCM

P2122 : 00 : 2F

★ PCM

P2127 : 00 : 2F

★ PCM

P2138 : 00 : 6D

★ PSCM

U0401 : 00 : 28

★ RCM

B00A0 : 68 : 08

TSB

☐ ⚠ Invalid Data Received From ECM/PCM 'A'

☐ ⚠ Driver Side LED

☐ ⚠ Adaptive Cruise Control

☐ ⚠ Invalid Data Received From ECM/PCM 'A'

☐ ⚠ Invalid Data Received From ECM/PCM 'A'

☐ ⚠ Throttle/Pedal Position Sensor/Switch 'D' Circuit Low

☐ ⚠ Throttle/Pedal Position Sensor/Switch 'E' Circuit Low

☐ ⚠ Throttle/Pedal Position Sensor/Switch 'D'/'E' Voltage Correlation

☐ ⚠ Invalid Data Received From ECM/PCM 'A'

☐ ⚠ Occupant Classification System

Time : 03:45 PM

Odometer : 2246 mi

 Clear Alert - Powertrain System Fault

PCM

P2138 : 00 : AF

☐ ⚠ Throttle/Pedal Position Sensor/Switch 'D'/'E' Voltage Correlation

Time : 11:35 AM

Odometer : 2227 mi

 Existing Alert - Powertrain System Fault

 Clear Alert - Collision Assist Unavailable

Show Details

PCM

P2127 : 00 : AF

CMR

B15E1 : 97 : 08

SSM

IPMA

U2108 : 68 : 2E

SOBDMC

U1011 : 86 : AF

ABS

U0401 : 64 : 2B

SOBDMC

P0887 : 00 : 28

SSM

PCM

P2138 : 00 : AF

ABS

U0594 : 64 : 2B

PSCM

U023A : 00 : 28

ABS

U0401 : 00 : 2A

PSCM

U0415 : 00 : 28

CMR

B115E : 97 : 08

SSM

SOBDMC

P1A13 : 00 : AF

☐ ⚠ Throttle/Pedal Position Sensor/Switch 'E' Circuit Low

☐ ⚠ Driver Side LED

☐ ⚠ Adaptive Cruise Control

☐ ⚠ Invalid Internal Control Module Monitoring Data Received from ECM/PCM

☐ ⚠ Invalid Data Received From ECM/PCM 'A'

☐ ⚠ TCM Power Relay Control Circuit High

☐ ⚠ Throttle/Pedal Position Sensor/Switch 'D'/'E' Voltage Correlation

☐ ⚠ Invalid Data Received From Hybrid/EV Powertrain Control Module 'A'

☐ ⚠ Lost Communication With Image Processing Module 'A'

☐ ⚠ Invalid Data Received From ECM/PCM 'A'

☐ ⚠ Invalid Data Received From Anti-Lock Brake System (ABS) Control Module

☐ ⚠ Camera Module

☐ ⚠ Hybrid Powertrain Control Module - Regenerative Braking Disabled

Time : 11:32 AM
Odometer :
2225 mi



New Alert -
Collision Assist
Unavailable

[Show](#)
[Details](#)



Existing Alert -
Powertrain
System Fault

[Show](#)
[Details](#)

PCM		P2127 : 00 : AF	
CMR		B15E1 : 97 : 08	SSM
IPMA		U2108 : 68 : 2E	
SOBDMC		U1011 : 86 : AF	
ABS		U0401 : 64 : 2B	
SOBDMC		P0887 : 00 : 28	SSM
PCM		P2138 : 00 : AF	
ABS		U0594 : 64 : 2B	
PSCM		U023A : 00 : 28	
ABS		U0401 : 00 : 2A	
PSCM		U0415 : 00 : 28	
CMR		B115E : 97 : 08	SSM
SOBDMC		P1A13 : 00 : AF	

- ☐ Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐ Driver Side LED
- ☐ Adaptive Cruise Control
- ☐ Invalid Internal Control Module Monitoring Data Received from ECM/PCM
- ☐ Invalid Data Received From ECM/PCM 'A'
- ☐ TCM Power Relay Control Circuit High
- ☐ Throttle/Pedal Position Sensor/Switch 'D'/'E' Voltage Correlation
- ☐ Invalid Data Received From Hybrid/EV Powertrain Control Module 'A'
- ☐ Lost Communication With Image Processing Module 'A'
- ☐ Invalid Data Received From ECM/PCM 'A'
- ☐ Invalid Data Received From Anti-Lock Brake System (ABS) Control Module
- ☐ Camera Module
- ☐ Hybrid Powertrain Control Module - Regenerative Braking Disabled

Time : 11:23 AM
Odometer :
2220 mi



New Alert -
Powertrain
System Fault

[Show](#)
[Details](#)

★ ABS		U0401 : 00 : 2A	
★ ABS		U0594 : 64 : 2B	
★ ABS		U0401 : 64 : 2B	
★ IPMA		U2108 : 68 : 2E	
★ PCM		P2138 : 00 : AF	
★ PCM		P2127 : 00 : AF	
★ SOBDMC		P1A13 : 00 : AF	
★ SOBDMC		U1011 : 86 : AF	
CMR		B15E1 : 97 : 08	SSM
CMR		B115E : 97 : 08	SSM
PSCM		U023A : 00 : 28	
PSCM		U0415 : 00 : 28	
SOBDMC		P0887 : 00 : 28	SSM

- ☐ Invalid Data Received From ECM/PCM 'A'
- ☐ Invalid Data Received From Hybrid/EV Powertrain Control Module 'A'
- ☐ Invalid Data Received From ECM/PCM 'A'
- ☐ Adaptive Cruise Control
- ☐ Throttle/Pedal Position Sensor/Switch 'D'/'E' Voltage Correlation
- ☐ Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐ Hybrid Powertrain Control Module - Regenerative Braking Disabled
- ☐ Invalid Internal Control Module Monitoring Data Received from ECM/PCM
- ☐ Driver Side LED
- ☐ Camera Module
- ☐ Lost Communication With Image Processing Module 'A'
- ☐ Invalid Data Received From Anti-Lock Brake System (ABS) Control Module
- ☐ TCM Power Relay Control Circuit High

Time : 11:21 AM
Odometer :
2218 mi



Clear Alert -
Powertrain
System Fault

★	ABS		U0401 : 00 : 68	
★	ABS		U0594 : 64 : 2A	
★	ABS		U0401 : 64 : 2A	
★	IPMA		U2108 : 68 : 28	
★	PCM		P2127 : 00 : 2C	
★	PSCM		U0415 : 00 : 28	
★	SOBDMC		U1011 : 86 : 2C	
★	SOBDMC		P1A13 : 00 : 2C	
★	SOBDMC		P0887 : 00 : 28	SSM
	CMR		B15E1 : 97 : 08	SSM
	CMR		B115E : 97 : 08	SSM
	PSCM		U023A : 00 : 28	

- ☐ Invalid Data Received From ECM/PCM 'A'
- ☐ Invalid Data Received From Hybrid/EV Powertrain Control Module 'A'
- ☐ Invalid Data Received From ECM/PCM 'A'
- ☐ Adaptive Cruise Control
- ☐ Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐ Invalid Data Received From Anti-Lock Brake System (ABS) Control Module
- ☐ Invalid Internal Control Module Monitoring Data Received from ECM/PCM
- ☐ Hybrid Powertrain Control Module - Regenerative Braking Disabled
- ☐ TCM Power Relay Control Circuit High
- ☐ Driver Side LED
- ☐ Camera Module
- ☐ Lost Communication With Image Processing Module 'A'

Time : 11:01 AM
Odometer :
2213 mi



New Alert -
Powertrain
System Fault

[Show
Details](#)

PCM		P2127 : 00 : AF	
IPMA		U2108 : 68 : 2F	
CMR		B15E1 : 97 : 08	SSM
PSCM		U023A : 00 : 28	
CMR		B115E : 97 : 08	SSM

- ☐ Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐ Adaptive Cruise Control
- ☐ Driver Side LED
- ☐ Lost Communication With Image Processing Module 'A'
- ☐ Camera Module

Time : 10:31 AM
Odometer :
2191 mi



Clear Alert -
Powertrain
System Fault

PCM		P2127 : 00 : AF	
IPMA		U2108 : 68 : 2F	
CMR		B15E1 : 97 : 08	SSM
PSCM		U023A : 00 : 28	
CMR		B115E : 97 : 08	SSM

- ☐ Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐ Adaptive Cruise Control
- ☐ Driver Side LED
- ☐ Lost Communication With Image Processing Module 'A'
- ☐ Camera Module

June 12, 2024

☐ Select All

Time : 01:19 PM

Odometer : 2190 mi



New Alert - Powertrain System Fault

[Show Details](#)

★	CMR		B115E : 97 : 08	SSM
★	CMR		B15E1 : 97 : 08	SSM
★	IPMA		U2108 : 68 : 2F	
★	PCM		P2127 : 00 : AF	
★	PSCM		U023A : 00 : 28	

- ☐  Camera Module
- ☐  Driver Side LED
- ☐  Adaptive Cruise Control
- ☐  Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐  Lost Communication With Image Processing Module 'A'

June 03, 2024

☐ Select All

Time : 01:56 PM

Odometer : 2126 mi

★	CMR		B115E : 97 : 0C	SSM
★	CMR		B15E1 : 97 : 0C	SSM
★	PSCM		U023A : 00 : 2E	

- ☐  Camera Module
- ☐  Driver Side LED
- ☐  Lost Communication With Image Processing Module 'A'

Time : 12:46 PM

Odometer : 2126 mi

★	CMR		B15E1 : 97 : 8F	SSM
★	PSCM		U023A : 00 : 28	

- ☐  Driver Side LED
- ☐  Lost Communication With Image Processing Module 'A'

May 29, 2024

☐ Select All

Time : 11:47 AM

Odometer : 1924 mi

★	PSCM		U023A : 00 : 2C	
---	------	--	-----------------	--

- ☐  Lost Communication With Image Processing Module 'A'

Time : 09:04 AM
Odometer :
1822 mi

 No DTCs Present

Time : 09:00 AM
Odometer :
1821 mi

★	ABS		C0609 : 01 : 68	
★	ABS		U0401 : 86 : 28	
★	ABS		C2008 : 13 : 28	
★	ABS		C003A : 01 : 28	
★	ABS		C0037 : 01 : 28	
★	ABS		C2007 : 13 : 28	
★	ABS		C0609 : 13 : 28	
★	BECM		U0100 : 00 : 28	
★	CMR		B15E1 : 97 : 0C	SSM
★	DCDC		U0100 : 00 : 28	
★	IPMA		U2108 : 68 : 28	
★	IPMA		U0401 : 86 : 28	
★	OCSM		U0401 : 00 : 28	
★	PCM		P2122 : 00 : 2F	
★	PCM		P2127 : 00 : 2F	
★	PSCM		U0401 : 00 : 28	
★	RCM		B00A0 : 68 : 08	TSB
	ABS		U3001 : 68 : 28	SSM

- ☐  Park Brake Switch Circuit
- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Left Motor
- ☐  Right Rear Wheel Speed Sensor
- ☐  Left Rear Wheel Speed Sensor
- ☐  Right Motor
- ☐  Park Brake Switch Circuit
- ☐  Lost Communication With ECM/PCM 'A'
- ☐  Driver Side LED
- ☐  Lost Communication With ECM/PCM 'A'
- ☐  Adaptive Cruise Control
- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Throttle/Pedal Position Sensor/Switch 'D' Circuit Low
- ☐  Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Occupant Classification System
- ☐  Control Module Improper Shutdown Performance

Time : 02:03 PM
Odometer :
1821 mi

 Clear Alert -
Powertrain
System Fault

★	ABS		U3001 : 68 : 28	SSM
★	IPMA		U2108 : 68 : 2C	
★	PCM		P2127 : 00 : 6D	
	CMR		B15E1 : 97 : 08	SSM
	PSCM		U0452 : 00 : 28	
	PSCM		U0415 : 00 : 28	

- ☐  Control Module Improper Shutdown Performance
- ☐  Adaptive Cruise Control
- ☐  Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐  Driver Side LED
- ☐  Invalid Data Received From Restraints Control Module
- ☐  Invalid Data Received From Anti-Lock Brake System (ABS) Control Module

May 23, 2024

Time : 05:22 PM

Odometer : 1821 mi

 New Alert - Powertrain System Fault

[Show Details](#)

★	IPMA		U2108 : 68 : 2F	
★	PCM		P2127 : 00 : AF	
★	PSCM		U0415 : 00 : 28	
★	PSCM		U0452 : 00 : 28	
	CMR		B15E1 : 97 : 08	SSM

- ☐ Select All
- ☐ 

 Adaptive Cruise Control
- ☐ 

 Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐ 

 Invalid Data Received From Anti-Lock Brake System (ABS) Control Module
- ☐ 

 Invalid Data Received From Restraints Control Module
- ☐ 

 Driver Side LED

May 21, 2024

Time : 11:27 AM

Odometer : 1763 mi

★	CMR		B15E1 : 97 : 08	SSM
★	PSCM		U0415 : 00 : 2C	
★	PSCM		U0452 : 00 : 2C	

- ☐ Select All
- ☐ 

 Driver Side LED
- ☐ 

 Invalid Data Received From Anti-Lock Brake System (ABS) Control Module
- ☐ 

 Invalid Data Received From Restraints Control Module

May 20, 2024

Time : 09:30 AM

Odometer : 1713 mi

★	CMR		B15E1 : 97 : 0E	SSM
---	-----	--	-----------------	-----

- ☐ Select All
- ☐ 

 Driver Side LED

Time : 04:49 PM
Odometer :
1712 mi

 Clear Alert -
Powertrain
System Fault

PCM		P2127 : 00 : AF	SSM
IPMA		U2108 : 68 : 2F	
SOBDMC		P0887 : 00 : 2C	
SOBDMC		U1011 : 86 : AF	
ABS		U0401 : 64 : 2B	
PCM		P2138 : 00 : AF	
ABS		U0594 : 64 : 2B	
ABS		U0401 : 00 : 2A	
SOBDMC		P1A13 : 00 : AF	

- ☐  Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐  Adaptive Cruise Control
- ☐  TCM Power Relay Control Circuit High
- ☐  Invalid Internal Control Module Monitoring Data Received from ECM/PCM
- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Throttle/Pedal Position Sensor/Switch 'D'/'E' Voltage Correlation
- ☐  Invalid Data Received From Hybrid/EV Powertrain Control Module 'A'
- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Hybrid Powertrain Control Module - Regenerative Braking Disabled

Time : 02:32 PM
Odometer :
1711 mi

★ ABS		U0594 : 64 : 2B	SSM
★ ABS		U0401 : 64 : 2B	
★ SOBDMC		P1A13 : 00 : AF	
★ SOBDMC		P0887 : 00 : 2C	
ABS		U0401 : 00 : 2A	
IPMA		U2108 : 68 : 2F	
PCM		P2127 : 00 : AF	
PCM		P2138 : 00 : AF	
SOBDMC		U1011 : 86 : AF	

- ☐  Invalid Data Received From Hybrid/EV Powertrain Control Module 'A'
- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Hybrid Powertrain Control Module - Regenerative Braking Disabled
- ☐  TCM Power Relay Control Circuit High
- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Adaptive Cruise Control
- ☐  Throttle/Pedal Position Sensor/Switch 'E' Circuit Low
- ☐  Throttle/Pedal Position Sensor/Switch 'D'/'E' Voltage Correlation
- ☐  Invalid Internal Control Module Monitoring Data Received from ECM/PCM

Time : 02:01 PM
Odometer :
1711 mi

 Existing Alert -
Powertrain
System Fault

[Show Details](#)

★ ABS		U0401 : 00 : 2A
★ ABS		U0594 : 64 : 2A
★ ABS		U0401 : 64 : 2A
★ PCM		P2138 : 00 : AF
★ SOBDMC		P1A13 : 00 : AE
★ SOBDMC		U1011 : 86 : AF

- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Invalid Data Received From Hybrid/EV Powertrain Control Module 'A'
- ☐  Invalid Data Received From ECM/PCM 'A'
- ☐  Throttle/Pedal Position Sensor/Switch 'D'/'E' Voltage Correlation
- ☐  Hybrid Powertrain Control Module - Regenerative Braking Disabled
- ☐  Invalid Internal Control Module Monitoring Data Received from ECM/PCM

IPMA | U2108 : 68 : 2F

☐  Adaptive Cruise Control

PCM | P2127 : 00 : AF

☐  Throttle/Pedal Position Sensor/Switch 'E' Circuit Low

Time : 01:58 PM

Odometer : 1711 mi

 New Alert - Powertrain System Fault

Show Details

★ IPMA | U2108 : 68 : 2F

★ PCM | P2127 : 00 : AF

☐  Adaptive Cruise Control

☐  Throttle/Pedal Position Sensor/Switch 'E' Circuit Low

May 13, 2024

Time : 11:25 AM

Odometer : 1708 mi

 No DTCs Present

May 09, 2024

Time : 12:06 PM

Odometer : 1694 mi

★ BECM | P2C85 : 1E : 68

☐  Hybrid/EV Battery Voltage External Isolation Fault

☐ Select All

April 22, 2024

Time : 10:21 AM

Odometer : 1552 mi

CMR | B15E1 : 97 : 08 SSM

BECM | P2C85 : 1E : 6C

☐  Driver Side LED

☐  Hybrid/EV Battery Voltage External Isolation Fault

☐ Select All

April 17, 2024

Time : 06:58 PM

Odometer : 1397 mi

PSCM | U0415 : 00 : 28

CMR | B15E1 : 97 : 08 SSM

BECM | P2C85 : 1E : 6C

☐  Invalid Data Received From Anti-Lock Brake System (ABS) Control Module

☐  Driver Side LED

☐  Hybrid/EV Battery Voltage External Isolation Fault

☐ Select All

Time : 06:30 PM

Odometer : 1397 mi

CMR | B15E1 : 97 : 08 SSM

BECM | P2C85 : 1E : 6C

LDCMA | B124B : 12 : 28

PSCM | U0415 : 00 : 28

☐  Driver Side LED

☐  Hybrid/EV Battery Voltage External Isolation Fault

☐  Left Daytime Running Light

☐  Invalid Data Received From Anti-Lock Brake System (ABS) Control Module

April 16, 2024

Time : 11:13 AM
Odometer :
1299 mi

★	BECM		P2C85:1E : 6C	
★	CMR		B15E1: 97 : 08	SSM
★	LDCMA		B124B: 12 : 28	
★	PSCM		U0415: 00 : 28	
★	PSCM		U023A: 00 : 28	

- ☐ Select All
- ☐

 Hybrid/EV Battery Voltage External Isolation Fault
- ☐

 Driver Side LED
- ☐

 Left Daytime Running Light
- ☐

 Invalid Data Received From Anti-Lock Brake System (ABS) Control Module
- ☐

 Lost Communication With Image Processing Module 'A'

April 15, 2024

Time : 09:47 PM

OTA

OTA On-Vehicle
Activity-Update
Activation is
finished

Time : 09:44 PM

OTA

OTA On-Vehicle
Activity-Vehicle
Activation Start