

CUSTOMER

257649

ARROW The Right Choice



INVOICE

4001 South First Street
Abilene, TX 79605
Phone (325) 692-9500

HTGT RANCHES DBA TOBIN RANCH

PAGE 1

SERVICE ADVISOR: 8173 JOHN SCOTT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Includes details for STAR WHITE, 23, FORD F150, 20795/20795, T1097F.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL.

A FORD 24B56 INOPERATIVE FRONT PARKING SENSORS CAUSE:

MT24B56D IPMA software failed and/or IPMA module replacement

4979 BEEBE,ZACKARY LIC#: 002561331 WAF

2053.80 2053.80

S13RECALL IPMA is needed rvc RHJ7Q4TJ5A7XR

4979 BEEBE,ZACKARY LIC#: 002561331 WAF

0.00 0.00

FC: A70 04

PART#: 14G647

COUNT:

CLAIM TYPE: 24B56

AUTH CODE: RHJ7Q4TJ5A7XR

4979

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

Mobile repair tried to do the programming and ran into issues. Had to contact hotline for further assistance. Contact ID : 120950017 Ipma will not accept any form of programming whether an update, pmi, or as built. A battery charger was being used on all 3 days and attempts. At the time of the first 2 attempts the soc was above 70. It is currently at 65 and battery will be charged before trying again with new ipma. Performed another hard battery reset as requested. Reset bms. Used back door method for programming and ipma and it instantly went to turn ignition off procedure unsuccessful. Performed data collector as requested and it said procedure completed. [z-beebel][WEB] Performed loaded voltage drop test on all of the power circuits and ground circuits to the IPMA and the drop was less than 0.1 on all of them [z-beebel][WEB] Removed and replaced the IPMA and performed PMI, apim 360 update, ipma 360 alignment, and ipma front camera alignment Retest and all ok

Table with columns: WARRANTY DISCLAIMER, SHOP SUPPLY COSTS, DESCRIPTION, TOTALS. Includes text: ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE s. 70.001: The undersigned being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 3.609 of the Texas Business & Commerce Code until the amount due is paid.

CUSTOMER #: 902042

257649



HTGT RANCHES DBA TOBIN RANCH

INVOICE

4001 South First Street
Abilene, TX 79605
Phone (325) 692-9500

PAGE 2

SERVICE ADVISOR: 8173 JOHN SCOTT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Includes details for STAR WHITE 23 FORD F150 and work dates like 01JAN23 IS, 18NOV23 DD.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL.

Dealership selected No Reply Required when submitting these comments. [z-beebel] [WEB]

B FORD 22G06 HEATED STEERING WHEEL PERFORMANCE UPGRADE CAUSE:

22S06G 12" Display with Adaptive Steering:
Replace HVAC Module w
4979 BEEBE,ZACKARY LIC#: 002561331
WAF

119.81 119.81

FC: C20 42
PART#: 3F791
COUNT:
CLAIM TYPE: 22G06
AUTH CODE:
4979

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
performed recall FORD 22G06 HEATED STEERING WHEEL PERFORMANCE UPGRADE

C After mobile reprogramming multiple lights on Dash cross system traffic fault Blindspot fault front camera fault no pre-collision available check and advise
DIAG After mobile reprogramming multiple lights on Dash cross system traffic fault Blindspot fault front camera fault no pre-collision available check and advise

4979 BEEBE,ZACKARY LIC#: 002561331
INT

135.00 135.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

Table with columns: WARRANTY DISCLAIMER, SHOP SUPPLY COSTS, DESCRIPTION, TOTALS. Includes text: ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE s. 70.001: The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.

CUSTOMER #: 902042

257649



HTGT RANCHES DBA TOBIN RANCH

INVOICE

4001 South First Street
Abilene, TX 79605
Phone (325) 692-9500

PAGE 3

SERVICE ADVISOR: 8173 JOHN SCOTT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE, R.O. OPENED, READY, OPTIONS, SOLD-STK, DLR, ENG. Includes line items for labor and parts, and a summary row for ESTIMATE: 1,980.97.

Table with columns: WARRANTY DISCLAIMER, SHOP SUPPLY COSTS, DESCRIPTION, TOTALS. Includes a signature line for the customer and dealership representative, and a total amount of 0.00.

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE s. 70.001: The undersigned being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.